

Measurement of Appearance

[SJ-MM-015]

2014-08-04
REV.0

Quality Assurance

Test procedure

1. Do naked eye distinction after place the sample 10g onto white background
2. Determine [OK] or [NG] comparing flowability and lump to standard