

Measurement of Moisture(K.F.Method)

[SJ-MM-017]

2010-03-30

Supersedes prior issues

Quality Assurance

Test procedure

1. Take 1.0~1.5ml of sample into 3ml injector.
2. Measure moisture with Karl Fischer(870 & 860 KF).

Equipment



870 & 860 KF