

Measurement of Hydrophobicity

[SJ-MM-032]

2014-05-20

Supersedes prior issues

Quality Assurance

Test method

- ① Put water 100g and powder 2g into 200ml beaker
- ② Mix 600rpm, 30sec, and then observe transparency after 10min
- ③ Evaluate hydrophobicity according to below standard(1~5)
- ④ But, Evaluate hydrophobicity to lower value if the hydrophobicity is the middle of both standard
- ⑤ Evaluate hydrophobicity with reference

Equipment



Evaluation standard

