

Measurement of Hydrophobicity

[SJ-MM-020]

2014-08-04
REV.3

Quality Assurance

Test procedure

1. Mix EtOH 40g and distilled water 320g in fannel
2. Add powder 20g into 1)
3. Stir for 1 min at 2500rpm
4. Read the setting volume(ml) after leaving for 10 mins

